## Oil Field Environmental Incident Summary

**Date/Time of Notice:** 11/17/2015 14:52 Incident: 20151117145239 Responsible Party: EOG RESOURCES, INC. EOG RESOURCES, INC. Well Name: PARSHALL SECTION 30 NENW CENTRAL FACILITY Field Name: PARSHALL Well File #: Facility ID Number: 217522-01 **MOUNTRAIL Twp:** 152 **Rna:** 90 Sec: 30 Qtr: NE NW County: Location Description: Submitted By: Keith Kallberg Received By: Contact Person: Keith Kallberg 600 17TH ST STE 1000N DENVER, CO 80202 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Units Spilled Recovered Units Followup **Units** Oil **Brine** 24 **Barrels** 24 Barrels Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: NA

Friday, February 10, 2017

Page 1 of 2

Areal Extent:

NA

## Potential Environmental Impacts:

NA

## Action Taken or Planned:

Water transfer was shut down stopping the release. Vac truck was brought in to remove the free fluids and a cleanup crew has scraped and removed the affected material, fresh material was used to replace what had been removed.

Wastes Disposal Location: Fluids taken to SWD and the solids are being taken to Clean Harbors at

Sawyer ND.

Agencies Involved: MHA & TAT

## **Updates**

Date: 11/17/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.